UNITED DRILLING SERVICES COMPANY

Oxy -Geismar Well # 3 A
Drilling Report

REPORTED BY: Leroy Arabie

REPORT NO: 44

DATE: 09/25/2012

Well TD:		**Well TD Yesterday:**		**Footage Drilled:**	
Bit No:		**WGT. on Bit (000's):**		**Rotary RPM:**	
Pump SPM:		**Pump PSI:**		**Pump GPM:**	

Mud System:

Type: **FW** **SW**

Viscosity	
Mud Weight	
PV	
YP	
GEL	

Inclination Surveys

Depth	Angle

Csg Depths	GL	RKB

Activities Previous 24 Hours:

SAFETY MEETING:

OPERATIONS: **START TIME:** 6am **QUITTING TIME:** 6am 9/26/2012

ACTIVITIES:

Held safety meeting.
Ran Sonar Tool to 4041', tool stopped could not any deeper.
Logged well f / 3649' t / 4076'
Rigged down wireline truck.
Bleeding well down.

ESTIMATED TOTAL COST - **DAILY:** #REF! **COST TO DATE:** #REF!

REMARKS: Bled down 1153 bbls and pressure is holding at 840 psi from 850 since we started bleeding down well.Bled a total of 1500 bbls.of hydro-carbon.

Responsible Care®
Good Chemistry at Work