From:	Joe Ball
To:	Christen Willis
Subject:	BC 12-1-2012 PM Report
Date:	Sunday, December 02, 2012 11:15:40 AM
Attachments:	Tx Brine GP #6 12-1-2012.jpg
	Sinkhole afternoon of 12-1-2012.jpg
	Bayou Corne Checklist for DNR Personnel12-1-2012PM Report.xlsx

Sent: Saturday, December 01, 2012 3:59 PM Subject: 12-1-2012 PM Report

Remediation continues at sinkhole. Completed Tx Brine Geoprobe #5 and working on #6. Tx Brine GP #1 has 9psi. Oxy 3-A SITP 88psi, SICP 574psi. Tx Brine Vent Well #1 FTP 2psi, gas rate 41.5mcf/d. Tx Brine Vent Well #2 S/I. ORW #1 FTP 12psi, gas rate 24.38mcf/d. ORW #2 FTP 51.5psi, gas rate 30.19mcf/d. ORW #3 SITP 0psi. ORW #4 FTP 19psi, gas rate 7.13mcf/d.

This email communication may contain confidential information which also may be legally privileged and is intended only for the use of the intended recipients identified above. If you are not the intended recipient of this communication, you are hereby notified that any unauthorized review, use, dissemination, distribution, downloading, or copying of this communication is strictly prohibited. If you are not the intended recipient and have received this communication in error, please immediately notify us by reply email, delete the communication and destroy all copies.

CONFIDENTIALITY NOTICE