

Bayou Corne Checklist

Name: Danielle Duhe
 Date: 7/7/2013
 Napoleonville Field (7010) -- Assumption Parish, LA

	<u>Shut-In/Flowing</u>	<u>Tbg Pressure (psig)</u>	<u>Choke (/64")</u>	<u>Notes</u>
ORW #1	Shut-in	28		
ORW #2	Shut-in	2		
ORW #3	Shut-in	-		No pressure
ORW #4	Flowing	43	2	
ORW #5	Shut-in	19		
ORW #6	Flowing	38	2	
ORW #7	Shut-in	4		
ORW #8	Shut-in	8		
ORW #9	Shut-in	52		
ORW #10	Flowing	56	3	
ORW #11	Shut-in	8		
ORW #12	Flowing	11	1.5	
ORW #13	Shut-in	37		
ORW #14	Flowing	46	7	
ORW #15	Flowing	20	5	
ORW #16	Shut-in	25		
ORW #17	Shut-in	4		
ORW #18	Shut-in	42		
ORW #19	Flowing	56	0.5	
ORW #20		N/A		Proposed well
ORW #21	Shut-in	0		
ORW #22	Flowing	16	1	
ORW #23	Shut-in	23		
ORW #24	Flowing	56	1	
ORW #26	Shut-in	18		
ORW #27	Shut-in	-		No Pressure/ Locked & Secured
ORW #28	Shut-in	16		
ORW #29	Shut-in	40		
ORW #30	Shut-in	55		
ORW #31	Flowing	24	0.5	
ORW #32	Shut-in	22		
ORW #33	Shut-in	-		No Pressure/ Locked & Secured
ORW #36	Flowing	49	5	

	<u>Shut-In/Flowing</u>	<u>Tbg Pressure (psig)</u>	<u>Choke (/64")</u>	<u>Notes</u>
ORW #37	Flowing	35	1.5	Grass is high within the fenced area
ORW #38R	Shut-in	4		
ORW #39	Shut-in	52		
ORW #40	Flowing	27	2	
OGRW#1	Flowing	58	5	
	<u>Shut-in/Flowing (if applicable)</u>	<u>Tbg Pressure (psig)</u>	<u>Csg Pressure (psig)</u>	<u>Notes</u>
G-1	Shut-in	-	215	
OG #3-A	Shut-in	586	598	Oil/Grease on ladder is a hazard
OG #1	Shut-in	115.1	245	
TBC #1	Shut-in	30	24	
TBC #2	Shut-in	56	N/A	
TBC #3	Shut-in	-	-	No Pressure
BC-2	Shut-in	55	20	
<u>OG Water Well #3</u>			<u>Sinkhole</u>	
Flowing or Locked-Out? _____			Cumulative Vegetation Hauled Off: _____ loads of 25-yd roll off boxes	
Locked-out _____			Cumulative Oil Hauled Off: _____ bbls	
Notes:				Notes: No debris removal activity
<u>Additional Remarks</u>				
Steady consistent bubbling from multiple locations was noticed on the north-northwest side of Well Pad 3.				