

LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0

Serial Num 39252	Date June 29, 2012	Operator Floyd J. Karsten	Id K091
Lease Name GUS J LABARRE # 001		Address 403 City National Bank Bldg.	
Section: 047 Township: 12S Range: 13E		Houston , TX 77002-0000	
Parish ASSUMPTION		Phone	
Field Napoleonville Id: 7010		Contact No Contact Given	

A. INSPECTION REASON

REVISION

Request by Baton Rouge Office

Complaint #:

Order #:

B. FACILITY TYPE

Single Lease

Commingled: N

Permit no.:

Oil: N **Gas:** N **Both:** Y

C. WELL SITE

1. **IDENTIFICATION:** Passed

2. **CONDITION:** Passed

Violation(s):

Well Site Comments: Well P&A'd -- See remarks below

D. TANK BATTERY

1. **IDENTIFICATION:** Passed

Violation(s):

2. **CONTAINMEN** Passed

Type:

Reference well:

Violation(s):

3. **BLEEDERS** **Exist:** N/A Passed

Violation(s):

4. **PIPELINE SALES VALVES:** Passed

Transporter:

Violation(s):

5. **B S & W VALVES:** Passed

Violation(s):

6. **MECHANICAL ARRANGEMENT:** Passed

Violation(s):

7. **STRUCTURAL INTEGRITY OF STORAGE TANKS** Passed

Violation(s):

LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0

8. VENTING OF STORAGE TANK Passed

Violation(s):

Tank Battery Comments: no tank battery

E. FIRE HAZARD Passed

Violation(s):

Fire Comments:

F. DISCHARGE OF E&P Passed

Violation(s):

Discharge Status:

Discharge Comments:

G. DISPOSITION OF E&P

Site Id:

Permit No:

H. EXISTENT PITS: No

I. NO. OF WELLS ON LEASE:

REMARKS: 50' West of s/n 39252 bubbles were located and marked with 3/4" PVC pipe - GPS Reading of bubbles are: See Photo
N 30-00'08.9"
W 91-08'42.2"

THE OPERATOR'S REPRESENTATIVE SHALL SIGN THIS REPORT TO ACKNOWLEDGE RECEIPT OF HIS COPY, YOUR SIGNATURE CANNOT BE CONSTRUED AS AN ADMISSION OF GUILT FOR ANY VIOLATIONS CONTAINED IN THIS REPORT.

No Witness
Operator's Representative

June 29, 2012

IN COMPLIANCE Yes **Sealed:** N

SELMA OUBRE
Conservation Enforcement Agent

June 29, 2012

Sonris Id: 1287

Latitude (Deg/Min/Sec:) 30 0 9.2 Longitude (Deg/Min/Sec:) 91 8 41.9 GPS Position: SW

LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996
0



Subject: bubbles

Photo File Name: F596865964/008.JPG



Subject: well area

Photo File Name: F-2109197534/009.JPG