

# LEASE FACILITY INSPECTION REPORT

DNR/Office of Conservation

SRCN996  
0

<b>Serial Num</b> 90074	<b>Date</b> June 29, 2012	<b>Operator</b> Inactive Operator	<b>Id</b> 9999
<b>Lease Name</b> GUS J LABARRE # 001		<b>Address</b> No Address On Record.	
<b>Section:</b> 047 <b>Township:</b> 12S <b>Range:</b> 13E		N/A , ZZ 00000-0000	
<b>Parish</b> ASSUMPTION		<b>Phone</b>	
<b>Field</b> Napoleonville Id: 7010		<b>Contact</b> No Contact Given	

## A. INSPECTION REASON

## REVISION

**Request by** Baton Rouge Office

**Complaint #:**

**Order #:**

## B. FACILITY TYPE

Single Lease

**Commingled:** N

**Permit no.**

**Oil:** N

**Gas:** N

**Both:** N

## C. WELL SITE

1. **IDENTIFICATION:** Passed

2. **CONDITION:** Passed

**Violation(s):**

**Well Site Comments:** Well P&A'd - See remarks below

## D. TANK BATTERY

1. **IDENTIFICATION:** Passed

**Violation(s):**

2. **CONTAINMEN** Passed

**Type:**

**Reference well:**

**Violation(s):**

3. **BLEEDERS** **Exist:** N/A Passed

**Violation(s):**

4. **PIPELINE SALES VALVES:** Passed

**Transporter:**

**Violation(s):**

5. **B S & W VALVES:** Passed

**Violation(s):**

6. **MECHANICAL ARRANGEMENT:** Passed

**Violation(s):**

7. **STRUCTURAL INTEGRITY OF STORAGE TANKS** Passed

**Violation(s):**

**LEASE FACILITY INSPECTION REPORT**

DNR/Office of Conservation

SRCN996  
0

**8. VENTING OF STORAGE TANK**      Passed

**Violation(s):**

**Tank Battery Comments:**      No tank battery

**E. FIRE HAZARD**      Passed

**Violation(s):**

**Fire Comments:**

**F. DISCHARGE OF E&P**      Passed

**Violation(s):**

**Discharge Status:**

**Discharge Comments:**

**G. DISPOSITION OF E&P**

**Site Id:**

**Permit No:**

**H. EXISTENT PITS:**      No

**I. NO. OF WELLS ON LEASE:**     

**REMARKS:**      Area of bubbles 50' West of sn 90074 were marked with 3/4" PVC pipe -- See photos  
GPS reading of bubbles  
N 30-00'08.9"  
W 91-08'42.2"

THE OPERATOR'S REPRESENTATIVE SHALL SIGN THIS REPORT TO ACKNOWLEDGE RECEIPT OF HIS COPY, YOUR SIGNATURE CANNOT BE CONSTRUED AS AN ADMISSION OF GUILT FOR ANY VIOLATIONS CONTAINED IN THIS REPORT.

No Witness  
Operator's Representative

June 29, 2012

**IN COMPLIANCE Yes**      **Sealed: N**

SELMA OUBRE  
Conservation Enforcement Agent

June 29, 2012

Sonris Id: 1289

**Latitude (Deg/Min/Sec:) 30 0 9 Longitude (Deg/Min/Sec:) 91 8 42 GPS Position: NW**



**Subject: bubbles**

Photo File Name: F1643920180/008.JPG



**Subject: well area**

Photo File Name: F1417427780/010.JPG